


US EPA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared		3. Time Prepared		UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill		07/12/2012		1730			
4. Unit Name/Designators		5. Unit Leader			6. Operational Period :		
Operations Unit/Containment Branch Monitoring Group		Name: Dan Capone & Joe Victory (START/US EPA)			From:		07/12/2012 0700
		Position: Operations Section Chief			To:		07/12/2012 1600
7. Personnel Roster Assigned							
Name		ICS Position			DUTY CELL		
Dan Capone		Operations Section Chief					
Joe Victory		Operations Section Chief					
Rex Johnson		Director					
Dan Zahner		Field Team Lead / CBM Team #3					
8. Activity Log							
Activity Area		Morrow Lake Delta and Neck				LAT	LAT
						Various	Various
						(DD.MMMM)	(DD.MMMM)
OIL OBSERVED		EXTENT OF OIL IMPACTED AREA					
		DENSITY OF OIL /SHEEN					
Total Collection Points		NA					
Total Boom Deployed		None					
Activity		<p><u>Weston/START Containment Branch Monitoring Group (CBM-3) Team Activity:</u></p> <p>E-4 Control Boom System</p> <p>Boom E South</p> <ul style="list-style-type: none"> Inspected the boom using SWAT's underwater video camera and recording system. Inspections were completed every 25 feet along the boom with curtain. All curtain inspected was against the bottom of the channel with the exception of a stretch from the posts for about 75 feet which was about 6 inches above. The rest of the curtain needs to be adjusted up to the proper height. <p>Boom E North</p> <ul style="list-style-type: none"> Inspected the boom using SWAT's underwater video camera and recording system. Inspections were completed every 25 feet along the boom with curtain. All curtain inspected was against the bottom of the channel. About half of the curtain needs to be adjusted up to the proper height. <p>Boom D</p> <ul style="list-style-type: none"> Inspected the boom using SWAT's underwater video camera and recording system. Inspections were completed every 25 feet along the boom with curtain. All curtain inspected was against the bottom of the channel. 100 feet was adjusted to bring the curtain up to the proper height. 					

	<p>Boom F South</p> <ul style="list-style-type: none">• <p>The underwater video camera SWAT utilizes works very well. In most places we were able to see a good picture of the curtain against the bottom of the channel along with water depth, then follow the curtain up to the top and see what the water depth was at that point. A video was made at each 25 foot interval showing the curtain with water depths, direction, and temperature.</p>
Health and Safety Issues	
Comments	Work activity is logged in logbook CBM3.